SPORTSMITH™ _Product Support Bulletin_

Title: P0221093 Stairmaster 4000PT Spring Install Tip
Date: 2/28/08 ml

It is important to note that when installing a new pedal return spring on a Stairmaster 4000PT, the spring cannot be installed from the side of the pulley.

Incorrect routing of spring for installation

You must insert the end of the spring into the pulley groove

Correct routing of spring for installation

and around the pulley to complete installation.