



## Product Support Bulletin

**Title: Gapping of Monitor Pickup to Magnetic Disk on Flywheel of Concept 2 Rower Models A & C**

**Date: July 2013 ml**

When replacing the monitor pickup or flywheel sensor on a Concept 2 Rower Model A or Model C, it is important to note the proper clearance between the monitor pickup and the magnetic disk.

If the pickup doesn't have proper clearance, the monitor may not perform. You may need to disassemble and reposition the magnetic disk or a washer for proper clearance.

