




G2 Barbell Rack

Model: G2FW96-US

YEAR 2006

DRAWING # FW96-A03A

SERIAL # FW96

REV. 0.2

DATE: 5/4/2006



G2 Barbell Rack Parts List.xls

Ref #	JHT Parts No.	SAP Parts No.	Description	Q'ty	Unit
AB1	SP0801138AA	058197-AA	Frame Set - Left	1	PCS
AB2	SP0801139AA	058198-AA	Frame Set - Right	1	PCS
AG1	SP1003015B	025611-B	Connecting Tube Set - Lower	2	SET
AG4	SP1020002B	025657-B	Connecting Tube Set - Upper	1	SET
B10	MB0314001A	000554-A	Foot pad;Tube;;Rubber RUBBER	2	PCS
B11	MJ2822016A	056993-A	shock;;;45#;CAM;;FW96;FW96-B03A; 45#	20	PCS
B12	MB0501021AA	056312-AA	Elastomer;Plastic;; PU	20	PCS
B13	MZE0301014	004975-00	Insert Nut;ALS7-8125-3.8(0.5-3.8); ALS7-8125-3.8(0.5-3.8)	40	PCS
B14	ME0105012AB	004567-AB	Screw;Sink Hex Socket ;;M8x1.25Px25L;;;C M8X1.25PX25L	40	PCS
B15	MZE0111001AC	004693-AD	Screw;Flat Hex Socket;M8x1.25Px15L;Cr Pl M8X1.25PX15L	4	PCS
not shown	SM3905028A	058047-A	Hardware Kit FW96-G2	1	SET
not shown	MH0204590A	056844-A	Assembly Manual MX-FW96	1	PCS
not shown	MB06E1001A	001542-A	Touch-up Paint	1	PCS
V03	MG0302022A	006656-A	STICKER, SERIAL #	1	PCS
V04	MZE1201003A	020699-A	NAIL, 1/8" X 12.5L	2	EA
V05	MG0204119E	005990-E	Sticker, Matrix Logo	1	EA
Z01	MZE0502235A	020479-AB	WASHER φ10.2xφ22x2.0t	16	PCS
Z02	MZE0204028	004943-00	NYLON NUT M10X1.5P(CHROMATE TREATMENT)	10	PCS
Z03	MZE0104151AB	004518-AB	ROUND HEX SOCKET SCREW M10X1.5PX75L	10	PCS
Z11	MJ2802013B	008523-B	ARC WASHER;GM02-C62B;SS41 SS41	4	PCS