



VR CLIMBER

S/N 250000-250854

Part #	Description	Qty.
SW-33007	Arm, Slack switch actuator	1
HX-05041	Bumper, Frame-to-Crank Arm	2
HX-05127	Bumper, Under-Pedal	2
HB-44058	Bushing, Crank Arm Pivot Shaft	2
HB-44026	Bushing, Pedal Screw	2
AW-45031	Cable, Drive	2
AW-14094	Cable, Fan and Speaker	1
AW-45030	Cable, Return	2
AW-14089	Cable, Ribbon - monitor to CPU chassis	1
AW-14082	Cable, Ribbon - overlay to interconnect PCB	1
AW-14086	Cable, VGA	1
EC-26031	CD-ROM Drive	1
AX-45027	Chain	1
AX-61355	Clutch Pulley	2
AX-61374	Clutch Shaft & Sprocket Assy	1
AX-61444	CP board	1
AX-61430	CPU Chassis	1
AX-61365	Crank Arm, Left	1
AX-61366	Crank Arm, Right	1
EH-36008	Fan	1
HB-44052	Flange Bearing	1
BD-45029	Friction Belt	1
HX-05105	Grips, Handlebar	2
AX-61310	Interconnect PCB - used under steering box	1
AX-61408	Keypad & Upper Housing	1
AX-70010	Monitor kit, NOT AVAILABLE, bring to TELEVISION repair shop	1
AX-61342	Motor	1
AX-61032	Parallel Arm Assy	1
AX-61357	Pedal Assy	2
AX-61311	Personality board (order with cable #14095)	1
EC-51517	Pitch encoder disc	1
AD-26005	OBSOLETE Power Supply	1
DE-51384	RPM Disc	1
AX-61323	OBSOLETE RPM Sensor	1
HS-41043	Screw, Pedal	2
FM-51461	Shaft, Crank Pivot	1
FM-51462	Shaft, Parallel Arm	1
FM-51048	Shaft, Pedal	2
SK-17520	Slack Switch Kit, includes slack switch and cable	1
SW-33007	Slack switch actuator, Arm	1
AD-26023	Sound board (Sound Blaster)	1
HX-40027	Spring, Pedal Return	2
AX-71079	Steering Box Upgrade Kit	0
FS-61213	Switchplate Assy	1

REPAIR ONLY

AX-61356	Obsolete-Assy Clutch V5 C-221	Replaced by SK-16763	1
CW-05052	Transport Wheel, Front		2
PL-05053	Transport Wheel, Front - Insert(mounts in frame)		2
AD-26033	VGA board, (Pentium)		1
EC-51504	Yaw encoder disc		1
AX-61514	Yaw -or- Pitch Sensor (Quad Sensor)		2
AX-15085	World Pack CD v 2.2		1
LT-03021	Manual, Owner's		1

Notes:

All VR Climbers were built with Pentium Mother Boards