



G2 Accessory Rack	
Model: G2FW97P	YEAR 2006
DRAWING # FW97-A03B-01	
SERIAL # FW97	
REV. 0.2 DATE: 12/8/2006	

G2 Accessory Rack Parts List.xls

Ref #	JHT Parts No.	SAP Par #	Description	Specification	Q'ty	Unit
AB1	SP0801137AA	058196-AA	Frame Set - FW97-AB1;		1	PCS
B09	MJ2822016A	056993-A	shock45#		10	PCS
B10	MB0501021AA	056312-AA	Elastomer - Plastic		8	PCS
B13	MB0314001A	000554-A	Foot pad;Tube;;Rubber RUBBER		4	PCS
B16	062620-AA	062620-AA	Rubber Pad;Accent - 76X67X6(RUBBER)		1	PCS
B17	MZE0111001AC	004693-AD	Screw;Flat Hex Socket	M8X1.25PX15L	4	PCS
B19	ME0105012AB	004567-AB	Screw;Sink Hex Socket	M8X1.25PX25L	18	PCS
B20	MB0501023AA	056313-AA	Elastomer;SMALL PU		2	PCS
B22	MZE0301014	004975-00	Insert Nut		26	PCS
B23	MZE0112013AC	004714-AD	Screw;Umbrella Hex Scket	M6X1.0PX15L	5	PCS
B24	ME0204004	004925-00	NYLON NUT	M6X1.0P	5	PCS
B25	MJ4210001B	009259-B	CON Rod;Hang Ring;;SS41;;;;;FW95 SS41		4	PCS
B26	MJ4905005B	009385-B	Supt Rod;Hang Ring;;SS41;;;;;FW95 SS41		1	PCS
B27	MJ4905004B	009384-B	Supt Rod;;;SS41;;;;;FW95 SS41		1	PCS
B28	ME0906001A	005380-A	HANGING RING SS41		1	PCS
B29	MZE0112287AB	069801	SCREW, FLAT HEX SOCKET	M8X1.25PX8L	4	PCS
B30	ME0114054AC	004853-AC	Screw;Stopper;;M6x1.0Px5L;;;Cr Plate;; M6X1.0PX5L		1	PCS
KIT	MH0204589A	056843-A	Assembly Manual		1	PCS
KIT	MB06E1001A	001542-A	touch up paint		1	PCS